

**DANGER:**

UNLESS HOOK RAISES WHEN "UP" BUTTON IS PRESSED SEVERE HOIST DAMAGE AND A DROPPED LOAD MAY RESULT.


CORRECT IMPROPER HOOK DIRECTION BY INTERCHANGING INPUT POWER L1 AND L3 DO NOT CHANGE PUSHBUTTON WIRING.

**WARNING**

THIS EQUIPMENT MUST BE EFFECTIVELY GROUNDED ACCORDING TO APPLICABLE CODES.

**AVERTISSEMENT**

CET EQUIPEMENT DOIT ETRE MIS A LA TERRE EN ACCORDANCE AVEC LES NORMES EN VIGUEUR.



NO.	CHANGE	DATE	ITL.	WIRING DIAGRAM	208, 230, 460 or 575 VOLT
				3 PHASE 2-SPEED	
				A.C. SOLENOID BRAKE	
				BUDGET ELECTRIC HOIST	
				SC. -----	
		8/17/06		DR. RITTER	
				CK.	
				 division of Columbus McKinnon Corporation Muskegon, Michigan 49443	
				SHEET 4 OF 4 SHEETS	
				333213	